



1-1020



Dwugwint

A2

d	l	l2	l3	s	
M 6	50	37	11	*	100
	60	37	20	*	100
	70	37	25	*	100
	80	47	30	*	100
	90	47	40	*	100
	100	47	40	*	100
	120	47	50	*	100
	130	47	50	*	100
	140	47	50	*	100
	150	47	50	*	100
M 8	50	37	11	*	100
	60	37	20	*	100
	70	37	25	*	100
	80	37	30	6	100
	90	37	40	6	100
	100	47	40	6	100
	110	47	40	6	100
	120	47	50	6	100
	130	47	50	6	100
	140	47	50	6	100
M 10	60	37	37	*	100
	80	47	47	8	100
	100	57	57	8	100
	120	57	57	8	100
	140	57	57	8	50
	150	57	57	8	50
	160	57	57	8	50
	180	57	57	8	50
	200	57	57	8	50
	220	57	100	8	50
M 12	250	57	100	8	50
	80	57	20	*	50
	100	57	25	10	50
	120	57	40	10	50
	140	57	40	10	50
	160	57	80	10	50
	180	57	100	10	50
	200	57	100	10	50
	250	57	100	10	50
	300	100	150	10	50
350	100	205	*	50	

* Brak sześciokąta pomiędzy gwintami